

# Work Order (Bid Form)

Auditor: Scott Haislip (615) 274-2565 or (615) 424-2565

### **WORK ORDER INFORMATION**

Work Order Name: WO/10010MC1850/1

Work Order Type: Weatherization

**Audit Name: 10010MC1850** 

CLIENT INFORMATION	)/	V
--------------------	----	---

Client Name: Address:

**Client ID:** 10010MC1850 WESTMORELAND, TN 37186

Alt. Client ID:

#### **AGENCY INFORMATION**

Agency: Mid-Cumberland Community Action Agency Agency Phone: (615) 742-1113

Fax:

Address: P.O.Box 310, 233 Legend Drive, Suite 103

Lebanon, TN 37088-0310 Email Address:

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

SITE BUILT 1972 BRICK 1698 SQ FT LEAD PAINT LIKELY

Client Name: Client ID: 10010MC1850 Alt. Client ID:

## Measures

			Componen	ts		,	nspected
			Estimated	•		Actual	
cription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
MOKE ALARMS	Each	2					
		Measur	e Sub Total:			Sub Total:	
6 MIL VADOD BAD	DIED		Componen	to			nspected
6 MIL VAPOR BAR CONTRACTOR TO			Componen				nspected
CONTRACTOR TO	VERIFY	Otv	Estimated		Otv	Actual	Inspected
CONTRACTOR TO		<b>Qty</b> 1	•		Qty		nspected
CONTRACTOR TO	VERIFY <i>Units</i>	_	Estimated		Qty	Actual	
CONTRACTOR TO	VERIFY <i>Units</i>	_	Estimated		Qty	Actual	
CONTRACTOR TO	VERIFY <i>Units</i>	_	Estimated		Qty	Actual	
CONTRACTOR TO	VERIFY  Units  Each	1	Estimated Unit Cost			Actual Unit Cost	
CONTRACTOR TO	VERIFY  Units  Each	1	Estimated			Actual	
	MOKE ALARMS			MOKE ALARMS Each 2  Measure Sub Total:			

ι	SEAL PLUMBING PENETRA JNDER KITCHEN SINK	ATIONS		Componen	ıts		1	Inspected
Comment				Estimated	1		Actual	
# Material / Labo	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail						,		
			Moasur	e Sub Total:		] []	Sub Total:	
Field Notes:							L	
	SEAL PLUMBING PENETRA			Componen	its			Inspected
(	SEAL PLUMBING PENETRA JNDER BATHROOM VANIT COMMODE SUPPLY LINE (	Υ&		-				Inspected
	JNDER BATHROOM VANIT COMMODE SUPPLY LINE (	Υ&		Estimated		Qty	Actual	Inspected Total
Comment	JNDER BATHROOM VANIT COMMODE SUPPLY LINE (	Y & 2)	<b>Qty</b> 1	-	<u> </u>	Qty		
Comment # Material / Labo	JNDER BATHROOM VANIT COMMODE SUPPLY LINE (  Description / Comment	Y & 2) Units	Qty	Estimated	<u> </u>	Qty	Actual	
Comment  # Material / Labo Other	JNDER BATHROOM VANIT COMMODE SUPPLY LINE (  Description / Comment	Y & 2) Units	Qty	Estimated	<u> </u>	Qty	Actual	
Comment  # Material / Labo Other	JNDER BATHROOM VANIT COMMODE SUPPLY LINE (  Description / Comment	Y & 2) Units	Qty	Estimated	<u> </u>	Qty	Actual	
Comment  # Material / Labo Other	JNDER BATHROOM VANIT COMMODE SUPPLY LINE (  Description / Comment	Units Each	<b>Qty</b> 1	Estimated	<u> </u>		Actual	
Comment  # Material / Labo Other	JNDER BATHROOM VANIT COMMODE SUPPLY LINE (  Description / Comment	Units Each	<b>Qty</b> 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 5 WEA	THER STRIP FRONT &	BACK		Componen	ts		1	Inspecte
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
Doors	WEATHER STRIP	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 6 ADD Comment	DOOR SWEEP TO ALL	_ 3 DOOR	S	Componen Estimated			Actual	Inspecte
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Doors	DOOR SWEEP	Each	1					
Other Detail								
				-		1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:		,	Sub Total:	

	AL AROUND THE WALL	AC UNIT		Componen	ts		ı	Inspecte
Comment				Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	-			Unit Cost	TOTAL	Qiy	Unit Cost	TOLAT
Other	AIR SEALING	Each	1					
Other Detail						_	<u> </u>	
			Measur	e Sub Total:		] ;	Sub Total:	
Field Notes:								
Massura & SE	AL CRACKS ALONG THE	F FI OOR		Componen	te			Inspecte
	AL CRACKS ALONG THI LDING & CRACKS AT C		OF	Componen	ts		ı	Inspecte
МО			OF	Componen	ts		ı	Inspecte
MO TUI	LDING & CRACKS AT C		OF	Componen	ts		I	Inspecte
MO TUI	LDING & CRACKS AT C		OF	Componen  Estimated			Actual	Inspecte
MO TUI Comment	LDING & CRACKS AT C		OF Qty			Qty		Inspecte
MO TUI Comment	LDING & CRACKS AT C 3 & WALL	ORNERS		Estimated	<u> </u>	Qty	Actual	
MO TUI Comment # Material / Labor Other	LDING & CRACKS AT C B & WALL Description / Comment	ORNERS Units	Qty	Estimated	<u> </u>	Qty	Actual	
MO TUI Comment # Material / Labor	LDING & CRACKS AT C B & WALL Description / Comment	ORNERS Units	Qty	Estimated	<u> </u>	Qty	Actual	
MO TUI Comment # Material / Labor Other	LDING & CRACKS AT C B & WALL Description / Comment	ORNERS Units	Qty	Estimated	<u> </u>	Qty	Actual	
MO TUI Comment # Material / Labor Other	LDING & CRACKS AT C B & WALL Description / Comment	Units Each	<b>Qty</b> 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
MO TUI Comment # Material / Labor Other	LDING & CRACKS AT C B & WALL Description / Comment	Units Each	<b>Qty</b> 1	Estimated	<u> </u>		Actual	
MO TUI Comment # Material / Labor Other	LDING & CRACKS AT C B & WALL Description / Comment	Units Each	<b>Qty</b> 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
MO TUI Comment # Material / Labor Other Other Detail	LDING & CRACKS AT C B & WALL Description / Comment	Units Each	<b>Qty</b> 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
MO TUI Comment # Material / Labor Other Other Detail	LDING & CRACKS AT C B & WALL Description / Comment	Units Each	<b>Qty</b> 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

	AL CRACKS ALONG FLO STER BATHROOM	OOR IN		Componen	ts			nspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measure	Sub Total:		] ;	Sub Total:	
	ic Ins. R-30 OF ATTIC FLOORED FOI RACTOR TO VERIFY	R STORA		Componen  Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1698		rotar	Qty		Total
Other Detail								
			Measure	Sub Total:			Sub Total:	
Field Notes:								

FO VERIFY  ion / Comment Units ulation - SqFt ss Batts - R-19	1264	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
ulation - SqFt	1264	Unit Cost			Unit Cost	Total
ulation - SqFt	1264		Total			Total
•		e Sub Total:			Sub Total:	
	Measure	e Sub Total:			Sub Total:	
	Measure	Sub Total:			Sub Total:	
	Measure	e Sub Total:			Sub Total:	
	Measure	e Sub Total:			Sub Total:	
(S					Antoni	
	_	Unit Cost	Total	Qty	Unit Cost	Total
Y LID Each	1					
	Measure	e Sub Total:			Sub Total:	
ti	RS	tion / Comment Units Qty	RS  Estimated tion / Comment Units Qty Unit Cost	Estimated tion / Comment Units Qty Unit Cost Total	Estimated tion / Comment Units Qty Unit Cost Total Qty	Estimated Actual tion / Comment Units Qty Unit Cost Total Qty Unit Cost

	AZE 7 WOOD WINDOWS HOUSE	ON FRO	NT	Componen	ts			Inspected
Comment 36" X 5 32" X 4	5"							
CONTI	OTOTOTO VERM T			Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Windows	WINDOW GLAZING	Each	1					
Other Detail						_		
			Measur	e Sub Total:			Sub Total:	
Measure 14 MA	STIC SEAL REGISTERS	& RETUR	N	Componen	fe .			Inspected
PAN	STIC SEAL REGISTERS N READING 0.5-2.0	& RETUR	N,	Componen	ts			Inspected
PAN		& RETUR	N,	<b>Componen</b> Estimated			Actual	Inspected
PAN Comment		& RETUR	N,	•		Qty		Inspected
PAN Comment	N READING 0.5-2.0  Description / Comment			Estimated		Qty	Actual	
PANComment # Material / Labor	N READING 0.5-2.0  Description / Comment	Units	Qty	Estimated		Qty	Actual	
PANComment  # Material / Labor Heating Equipme	N READING 0.5-2.0  Description / Comment	Units	Qty	Estimated		Qty	Actual	
PANComment  # Material / Labor Heating Equipme	N READING 0.5-2.0  Description / Comment	Units	Qty	Estimated		Qty	Actual	Inspected
PANComment  # Material / Labor Heating Equipme	N READING 0.5-2.0  Description / Comment	Units Each	<b>Qty</b> 1	Estimated			Actual	
PANComment  # Material / Labor Heating Equipme	N READING 0.5-2.0  Description / Comment	Units Each	<b>Qty</b> 1	Estimated Unit Cost			Actual Unit Cost	
PAN Comment  # Material / Labor Heating Equipme Other Detail	N READING 0.5-2.0  Description / Comment	Units Each	<b>Qty</b> 1	Estimated Unit Cost			Actual Unit Cost	

	TALL AIR FILTER & LE <i>I</i> MEOWNER	AVE 5 FOI	₹	Componen	its		7	nspected
Comment 20" X 3	0"							
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipmen	n AIR FILTERS	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 16 DHV	W TANK INSULATION							
				Componen				nspected
# Material / Labor	Description / Comment	Units	Ofv	Estimated	1	Ofv	Actual	
# Material / Labor Insulation	Description / Comment  DHW TANK INSULATION	<i>Units</i> Each	<b>Qty</b> 1	-		Qty		Total
	DHW TANK			Estimated	1	Qty	Actual	
Insulation	DHW TANK			Estimated	1	Qty	Actual	
Insulation	DHW TANK			Estimated	1	Qty	Actual	
	DHW TANK	Each	1	Estimated	1		Actual	

Measure 17 DWH Pipe Insulation			Components						Inspected	
C	Comment									
					Estimated	1		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1						
2	Labor	DHW Pipe Insulation	Each	1						
(	Other Detail			1	] [		7			
				Measur	e Sub Total:		] ;	Sub Total:		
	Field Notes:									
			Work O	rder Gra	and Total:		Gran	d Total:		